



Framing Screw Pan Phillips Self Drill Phosphate Finish

CAT. NO.	SIZE	U/M	STD. BOX	STD. CTN.	WT./UM
----------	------	-----	----------	-----------	--------

005187	6 x 7/16"	C	100	4000	0.24
--------	-----------	---	-----	------	------



Framing Screw Pan Phillips Self Drill Phosphate Bulk Pack

CAT. NO.	SIZE	U/M	STD. BOX	STD. CTN.	WT./UM
----------	------	-----	----------	-----------	--------

005188	6x7/16" (M)	C	15000	0	0.24
--------	-------------	---	-------	---	------



Zinc Tapping Screw Indent Hex Washer Head Slot

CAT. NO.	SIZE	U/M	STD. BOX	STD. CTN.	WT./UM
060005	#12 X 5/8" A	C	100	3000	0.74
060006	#6 X 1-1/4" A	C	100	3000	0.45
060007	#6 X 3/8" AB	C	100	4000	0.20
060008	#6 X 1/2" AB	C	100	4000	0.25
060009	#6 X 3/4" AB	C	100	4000	0.32
060010	#6 X 1" A	C	100	4000	0.38
060011	#6 X 1-1/2" A	C	100	3000	0.52
060012	#8 X 3/8" AB	C	100	4000	0.28
060013	#8 X 1/2" AB	C	100	4000	0.34
060014	#8 X 5/8" AB	C	100	4000	0.36
060015	#8 X 3/4" AB	C	100	4000	0.43
060016	#8 X 1" A	C	100	3000	0.53
060017	#8 X 1-1/4" A	C	100	3000	0.62
060018	#8 X 1-1/2" A	C	100	3000	0.73
060019	#8 X 2" A	C	100	3000	0.92
060020	#8 X 2-1/2" A	C	100	1000	1.13
060021	8 X 3" A"	C	100	1000	1.34
060022	#10 X 3/8" A"	C	100	4000	0.41
060023	#10 X 1/2" AB	C	100	4000	0.46
060024	#10 X 5/8" AB	C	100	4000	0.54
060025	#10 X 3/4" AB	C	100	3000	0.59
060026	#10 X 1" A	C	100	3000	0.73
060027	#10 X 1-1/4" A	C	100	3000	0.84
60028	#10 X 1-1/2" A	C	100	3000	0.97
060029	#10 X 2" A	C	100	1000	1.22
060030	#10 X 2-1/2" A	C	100	1000	1.45
060031	#10 X 3" A"	C	100	1000	1.70
060032	#12 X 1/2" AB	C	100	4000	0.63
060033	#12 X 3/4" AB	C	100	3000	0.81
060034	#12 X 1" A	C	100	3000	0.98
060035	#12 X 1-1/4" A	C	100	3000	1.14
060036	#12 X 1-1/2" A	C	100	3000	1.31

CAT. NO.	SIZE	U/M	STD. BOX	STD. CTN.	WT./UM
060037	#12 X 2" A	C	100	1000	1.61
060038	#12 X 2-1/2" A	C	100	1000	1.98
060039	#12 X 3" A	C	100	1000	2.33
060040	#14 X 3/4" AB	C	100	3000	1.23
060041	#14 X 1" A	C	100	3000	1.50
060042	#14 X 1-1/4" A	C	100	1000	1.69
060043	#14 X 1-1/2" A	C	100	1000	1.89
060044	#14 X 2" A	C	100	1000	2.42
060045	#14 X 2-1/2" A	C	100	1000	2.95
060046	#14 X 3" A	C	100	1000	3.49



Zinc Tapping Screw Indent Hex Washer Head Slot Zip Point

CAT. NO.	SIZE	U/M	STD. BOX	STD. CTN.	WT./UM
----------	------	-----	----------	-----------	--------

061016	#7 X 1/2"	C	100	4000	0.31
061031	#8 X 1/2"	C	100	4000	0.31
061033	#8 X 3/4"	C	100	4000	0.42
061035	#8 X 1"	C	100	3000	0.51



Zinc Tapping Screw Pan Combo (Slot/Phil)

CAT. NO.	SIZE	U/M	STD. BOX	STD. CTN.	WT./UM
----------	------	-----	----------	-----------	--------

061102	#6 X 3/8" AB	C	100	4000	0.17
061103	#6 X 1/2" AB	C	100	4000	0.20
061104	#6 X 5/8" AB	C	100	4000	0.24
061105	#6 X 3/4" AB	C	100	4000	0.27
061106	#6 X 1" A	C	100	4000	0.34
061107	#6 X 1-1/4" A	C	100	4000	0.42
061108	#6 X 1-1/2" A	C	100	3000	0.49
061109	#6 X 2" A	C	100	3000	0.64
061110	#8 X 3/8" AB	C	100	4000	0.28
061111	#8 X 1/2" AB	C	100	4000	0.31
061112	#8 X 5/8" AB	C	100	4000	0.35
061113	#8 X 3/4" AB	C	100	4000	0.41
061114	#8 X 1" A	C	100	4000	0.51
061115	#8 X 1-1/4" A	C	100	3000	0.61
061116	#8 X 1-1/2" A	C	100	3000	0.69
061117	#8 X 1-3/4" A	C	100	3000	0.81
061118	#8 X 2" A	C	100	3000	0.89
061119	#8 X 2-1/2" A	C	100	1000	1.10
061120	#8 X 3" A	C	100	1000	1.30
061121	#10 X 3/8" AB	C	100	4000	0.39
061122	#10 X 1/2" AB	C	100	4000	0.43
061123	#10 X 5/8" AB	C	100	4000	0.50
061124	#10 X 3/4" AB	C	100	4000	0.54
061125	#10 X 1" A	C	100	3000	0.69
061126	#10 X 1-1/4" A	C	100	3000	0.80
061127	#10 X 1-1/2" A	C	C100	3000	0.91