



INTERNATIONAL TOOL MANUFACTURING
71-08 51st Ave. Woodside, NY 11377

(718) 446-0711 • (800) 247-5696
Fax (718) 899-6553

X-Tend Your Drilling Depths!



X-Tendr™ - MAX to MAX SHANK ADAPTER

Part #	Description
XT6700	Adapter (1-3/16" x 7-1/2")
XT6750	Adapter Grease (Tube)

Drill Bit Diameter Must Be 1-1/4" Or Larger.



Shown: Spline Shaft

X-Tendr™ Extension Shafts

Part #	OAL	Shank
XT6701	12-1/2"	SDS-MAX
XT6702	30"	SDS-MAX
XT6703	44"	SDS-MAX
XT6708	12-1/2"	SPLINE
XT6709	30"	SPLINE

Drill bit extension system for all SDS-Max & Spline machines.

- ◆ Extend Any SDS-MAX Tool
- ◆ Quick & Safe Connection
- ◆ Simple To Use
- ◆ No Energy Loss
- ◆ No Weak Points
- ◆ Saves Time & Money
- ◆ Reduces Tool Requirements

How it works:

- X-Tendr™ Adapter has double locking SDS-MAX inputs.
- All EXTENSION SHAFTS have 1 SDS-MAX end which locks into X-Tendr Adapter. Other end can be inserted into either an SDS-MAX or Spline machine.
- Extend ANY SDS-MAX drill bit, core bit, concrete cutter, drill head, or chisel.
- Reach of X-Tendr™ system limited to 1 adapter and 1 extension.



1. Choose either SDS-MAX or SPLINE Drive and desired length Extension.




2. Attach X-Tendr™ Adaptor to SDS-MAX end of Extension.



3. Attach desired SDS-MAX Rotary Hammer Drill Bit, Core Bit, Tunnel Bore Drill or Chisel.

Drill Bit Diameter Must Be 1-1/4" Or Larger.


Use Your SDS-Plus Drill Bits In Larger SDS-MAX® Or Spline Drive Machines:



Adapter

SDS-MAX® to SDS-PLUS

Part #	Description
725MAX001	SDS-MAX To SDS-Plus Adapter



Adapter

Spline to SDS-PLUS

Part #	Description
725SP0001	Spline To SDS-Plus Adapter



Replacement Kit - FOR ADAPTERS

Part #	Description
715KIT001	Gaskets & Ball Bearings

